



October 31, 2005

05-RF-01006

John Rampe
Director
RFPO Closure Project Manager
DOE, RFPO

**ROCKY FLATS RESOURCE CONSERVATION AND RECOVERY ACT 2005 BIENNIAL
HAZARDOUS WASTE REPORT - DSC-052-05**

Dear John

Enclosed is the Resource Conservation and Recovery Act 2005 Biennial Hazardous Waste Report. The diskette containing the report, the RCRA Subtitle C Site Identification Form, with your signature and the Pollution Prevention Survey needs to be submitted to the Colorado Department of Public Health and Environment (CDPHE) on or before January 5, 2006. A January 5, 2006 date has been entered on the Site ID Form.

Also enclosed is a letter from CDPHE allowing the Site to use the 2003 Hazardous Waste Report and a program to enter the data for the 2005 information. A draft letter to CDPHE is included for your use.

If you have any questions regarding this submittal please contact me at 303-966-9877.

Sincerely,

David C. Shelton
Vice President
Environmental Systems and Stewardship

DAW:plh

Enclosure
As Stated

STATE OF COLORADO

Bill Owens, Governor
Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S.
Denver, Colorado 80246-1530
Phone (303) 692-2000
TDD Line (303) 691-7700
Located in Glendale, Colorado

Laboratory Services Division
8100 Lowry Blvd.
Denver, Colorado 80230-6928
(303) 692-3090

<http://www.cdphe.state.co.us>



Colorado Department
of Public Health
and Environment

June 22, 2005

Mr. David Shelton
Kaiser-Hill LLC
12101 Airport Way, Unit B
Broomfield, CO 80021-2583

RE: 2005 Annual Activity Report and HW Report
CO7890010526

Dear Mr. Shelton:


Per your phone request on June 20, 2005, enclosed are the 2005 Annual Activity Report and the 2003 Hazardous Waste Report that you can use for 2005 information. Please let us know if the invoice for post-closure activities for 2005 should be included in this invoice. The applicability and description of the annual fees are described in Section 100.31 of the Colorado Hazardous Waste Regulations (6 CCR 1007-3).

If you have any questions concerning these reports please contact Mira Neumiller at (303) 692-3350.

Sincerely,

Joyce Williams, Unit Leader
Hazardous Waste Compliance and Enforcement

CC: Steve Gunderson, CDPHE



January 5, 2006

Colorado Department of Public Health and Environment
Hazardous Materials and Waste Management Division
4300 Cherry Creek Drive South
Mail Code HMWMD-CP-B2
Denver, CO 80246-1530

Attention: Mira Neumiller

2005 BIENNIAL HAZARDOUS WASTE REPORT

The U.S. Department of Energy, Rocky Flats Project Office is submitting the enclosed 2005 Biennial Hazardous Waste Report information for the Rocky Flats Environmental Technology Site (EPA ID# CO7890010526). Enclosed is a 3.5-inch diskette containing the electronic transmittal files using the BRS State Format, a signed Site form, and the Pollution Prevention Survey. This information provides details on the hazardous and mixed waste generation, treatment and shipment activities for calendar year 2005.

Please call me at 303-966-6246 if you have any questions.

John Rampe
Closure Project Manager
Rocky Flats Project Office

Enclosures
AS Stated

MAIL THE COMPLETED FORM TO: The appropriate EPA Regional or State Office.	United States Environmental Protection Agency RCRA SUBTITLE C SITE IDENTIFICATION FORM		
1. Reason for Submittal (see instructions on page 9) MARK ALL BOX(ES) THAT APPLY	A. Reason for Submittal: <input type="checkbox"/> To provide initial notification (to obtain an EPA ID Number for hazardous waste, universal waste or used oil activities). <input checked="" type="checkbox"/> To provide subsequent notification (to update site identification information). <input type="checkbox"/> As a component of a First RCRA Hazardous Waste Part A Permit Application. <input type="checkbox"/> As a component of a Revised RCRA Hazardous Waste Part A Permit Application (Amendment #) <input checked="" type="checkbox"/> As a component of Hazardous Waste Report.		
2. Site EPA ID Number (see instructions on page 10)	EPA ID Number: CO7890010526		
3. SiteName (see instructions on page 11)	Site Name: Rocky Flats Env. Tech. Site-US DOE		
4. Site Location Information (see instructions on page 10)	Street Address: 10808 Hwy 93 16 miles NW of Denver		
	City, Town or Village: Golden		State: CO
	County Name: BOULDER		Zip Code: 80403
5. Site Land Type (see instructions on page 10)	Site Land Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other		
6. North American Industry Classification System (NAICS) Code(s) for the Site (see instructions on page 10)	A. 332995		B. None
	C.		D.
7. Site Mailing Address (see instructions on page 11)	Street or P.O. Box: 12101 Airport Way, Unit A		
	City, Town or Village: Broomfield		
	State: CO		
	Country: UNITED STATES		Zip Code: 80021
8. Site Contact Person (see instructions on page 11)	First Name: John MI: J		Last Name: Rampe
	Phone Number: 3039666245 Extension: NA		Email Address: john.rampe@rf.doe.gov
9. Operator and Legal Owner of the Site (see instructions on page 11 and 12)	Name of Site's Operator: U.S. Department of Energy (DOE)		Date Became Operator (mm/dd/yyyy): 10/12/2005
	Operator Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other		
	Name of Site's Legal Owner: DOE		Date Became Owner (mm/dd/yyyy): 07/10/1951
Owner Type: <input type="checkbox"/> Private <input type="checkbox"/> County <input type="checkbox"/> District <input checked="" type="checkbox"/> Federal <input type="checkbox"/> Indian <input type="checkbox"/> Municipal <input type="checkbox"/> State <input type="checkbox"/> Other			

9. Legal Owner (Continued) Address	Street or P.O. Box: 12101 Airport Way Unit A	
	City, Town or Village: Broofield	
	State: CO	
	Country: UNITED STATES	Zip Code: 80021

10. Type of Regulated Waste Activity (Mark "Yes" or "No" for all activities; complete an additional boxes as instructed)

A. Hazardous Waste Activities
Complete all parts for 1 through 6.

Y ☒ N ☐ 1. Generator of Hazardous Waste
If "Yes", choose only one of the following - a, b or c.

☒ a. LQG: Greater than 1000 kg/mo (2,200 lbs.) of non-acute hazardous waste; or

☐ b. SQG: 100 to 1000 kg/mo (220 - 2,200 lbs.) of non-acute hazardous waste; or

☐ c. CESQG: Less than 100 kg/mo (220 lbs.) of non-acute hazardous waste

In addition, indicate other generator activities.

Y ☐ N ☒ d. United States Importer of Hazardous Waste

Y ☒ N ☐ e. Mixed Waste (hazardous and radioactive) Generator

Y ☐ N ☒ 2. Transporter of Hazardous Waste

Y ☒ N ☐ 3. Treater, Storer or Disposer of Hazardous Waste (at your site)
Note: A hazardous waste permit is required for this activity.

Y ☐ N ☒ 4. Recycler of Hazardous Waste (at your site)

Y ☐ N ☒ 5. Exempt Boiler and/or Industrial Furnace

☐ a. Small Quantity On-Site Burner Exemption

☐ b. Smelting, Melting, Refining Furnace Exemption

Y ☐ N ☒ 6. Underground Injection Control

B. Universal Waste Activities

Y ☒ N ☐ 1. Large Quantity Handler of Universal Waste (accumulate 5,000 kg or more) [refer to your State regulations to determine what is regulated]. Indicate types of universal waste generated and/or accumulated at your site. If "Yes", mark all boxes that apply:

	<u>Generated</u>	<u>Accumulated</u>
a. Batteries	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. Pesticides	<input type="checkbox"/>	<input type="checkbox"/>
c. Thermostats	<input type="checkbox"/>	<input type="checkbox"/>
d. Lamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. Other (specify) Aerosol Cans	<input checked="" type="checkbox"/>	<input type="checkbox"/>
f. Other (specify) Electronic	<input checked="" type="checkbox"/>	<input type="checkbox"/>
g. Other (specify)	<input type="checkbox"/>	<input type="checkbox"/>

Y ☐ N ☒ 2. Destination Facility for Universal Waste
Note: A hazardous waste permit may be required for this activity.

C. Used Oil Activities
Mark all boxes that apply.

Y ☐ N ☒ 1. Used Oil Transporter
If "Yes", mark each that applies.

☐ a. Transporter

☐ b. Transfer Facility

Y ☐ N ☒ 2. Used Oil Processor and/or Re-refiner
If "Yes", mark each that applies.

☐ a. Processor

☐ b. Re-refiner

Y ☐ N ☒ 3. Off-Specification Used Oil Burner

Y ☐ N ☒ 4. Used Oil Fuel Marketer
If "Yes", mark each that applies.

☐ a. Marketer Who Directs Shipment of Off-Specification Used Oil to Off-Specification Used Oil Burner

☐ b. Marketer Who First Claims the Used Oil Meets the Specifications

11. Description of Hazardous Wastes (see instructions on page 16)

A. Waste Codes for Federally Regulated Hazardous Wastes. Please list the waste codes of the Federal hazardous wastes handled at your site. List them in the order they are presented in the regulations (e.g., D001, D003, F007, U112). Use an additional page if more spaces are needed.

D001	D002	D003	D004	D005	D006	D007
D008	D009	D010	D011	D018	D019	D021
D022	D026	D027	D028	D029	D030	D032

B. Waste Codes for State-Regulated (i.e., non-Federal) Hazardous Wastes. Please list the waste codes of the State-regulated hazardous wastes handled at your site. List them in the order they are presented in the regulations. Use an additional page if needed for more waste codes.

12. Comments (see instructions on page 17)

Section 11, Box A, D033, D034, D035, D036, D037, D038, D039, D040, D042, D043, F001, F002, F003, F004, F005, F006, F007, F008, F009, F039, P011, P012, P015, P016, P022, P028, P030, P043, P076, P078, P087, P098, P099, P106, P113, P119, P120, U002, U003, U004, U009, U020, U025, U027, U028, U031, U041, U042, U044, U050, U057, U069, U071, U075, U077, U078, U079, U080, U083, U103, U106, U107, U108, U112, U113, U117, U121, U122, U123, U130, U135, U144, U145, U151, U154, U159, U160, U161, U165, U188, U204, U210, U211, U213, U214, U215, U216, U217, U226, U227, U228, U234, U239, U240, U359.

13. Certification. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (see instructions on page 17)

Signature of owner, operator, or an authorized representative	Name and Official Title (type or print)	Date Signed (mm/dd/yyyy)
	John J Rampe, Director, Proj.	01/05/2006

Rocky Flats Environmental Technology Site
Company Name: Kaiser-Hill Company, L.L.C. / U.S. D.O.E.

EPA ID #: CO7890010526

2005 Hazardous Waste Minimization/Pollution Prevention Survey

Fill out this survey and return it with your completed 2005 Hazardous Waste Report by March 1, 2006

This brief survey is included with the 2005 Hazardous Waste Report to help determine your facility's compliance with the requirement to have a waste minimization program in place to reduce the volume, quantity and toxicity of waste at your facility. If you have questions regarding this survey, please contact Kirk Mills at (303) 692-2977 or

kirk.mills@state.co.us.

Please note, that your facility may be nominated for an Environmental Leadership Program Silver Level Achievement Award if the projects submitted rise to the level of this award. **Thank you! Your assistance is appreciated!**

1) Does your company/facility have an:

Environmental Policy? ☐ No ☒ Yes (attach policy)

Described in the K-H Environmental Management

Environmental Management System (EMS)? ☐ No ☒ Yes (if yes, please describe) Program Guidance Manual

A Quality Program? ☐ No ☒ Yes (if yes, please describe) _____

A systematic Energy Efficiency Program? ☐ No ☒ Yes (if yes, please describe) Immediate shutdown of utilities to uninhabited bldgs.

A reasonable understanding of the **total costs** of wastes/releases/toxics use? ☐ No ☒ Yes (if yes, please describe cost elements included) handling, characterization, inspections, containers, storage, certification, manifesting, reporting, transportation, and disposal.

2) Large Quantity Hazardous Waste Generators are statutorily required and certify on manifests that a program is in place to reduce the volume, quantity and toxicity of waste. (From the list below, check-off elements contained in the program at your facility):

☒ Assesses total costs of waste management for each significant waste stream

☒ Identifies types and amounts of waste generated by various processes and causes

☒ Prioritizes waste minimization options based on costs, benefits and feasibility

☒ Incorporates waste minimization into purchasing, marketing and product design

☒ Encourages employees to offer suggestions

☒ Periodically updates the plan and re-evaluates options

☐ Other (please describe) _____

☒ Provides employee training

☒ Uses a team approach for planning

☒ Sets waste minimization goals

3) Does your company/facility participate in any voluntary programs or networks such as the Environmental Leadership Program, Colorado Environmental Partnership, Energy Star, Wastewise or pertinent trade association? ☐ No ☒ Yes (if yes, please list) EPA WasteWise

4) In the past two years has your facility had a Pollution Prevention (P2) or Energy Efficiency (E2) assessment? No Yes - by: Internal Private consultant State Agency Federal Program Other _____

5) Which of the factors listed below limit or delay the initiation of new source reduction or recycling activities at your facility? (Please check all that apply)

☐ Insufficient capital for new equipment or to implement new practices

☐ Lack of technical information for specific production processes

☐ Technical concerns of the production process

☒ Source reduction/recycling is not economically feasible; cost savings will not recover capital investment fast enough or at all

☒ Waste minimization previously implemented; additional reductions currently not technically feasible

☒ Waste minimization previously implemented; additional reductions currently not economically feasible

☐ Waste minimization previously implemented; additional reductions currently not feasible due to regulatory requirements

☐ Product quality concerns

☐ Regulatory/permitting requirements

☐ Other _____

6) For more information, please check the appropriate boxes.

☐ General information on waste minimization, waste minimization plan development, and P2

☐ Technical assistance on industry or process specific P2 questions

☐ On-site non-enforcement P2 assessment or compliance assistance

☐ Colorado's Environmental Leadership Program



KAISER-HILL
COMPANY

Revision 1
March 2000
Page 1 of 1

ENVIRONMENTAL POLICY

POLICY

Environmental protection and enhancement is a core principle for the Kaiser-Hill Company, LLC at the Rocky Flats Environmental Technology Site (RFETS). Kaiser-Hill is committed to protecting, preserving and enhancing the environment and the health and safety of employees through implementation of the Site Environmental Stewardship program and demonstrated compliance with governing laws, permits and compliance agreements.


Kaiser-Hill and its subcontractors will conduct business with respect and care for the environment. Our Environmental Stewardship program goes beyond compliance with the law. It requires:

- integrating safe and sound environmental practices into our business decisions,
- continuously improving our practices in light of new understandings and technologies, and
- setting goals, and measuring and reporting our progress.

Kaiser-Hill pledges to integrate the following elements into our daily activities and decision-making processes as essential management elements:

1. Preserve and enhance the environmental quality of the Rocky Flats Site.
2. Reduce risks to human health and the environment during the closure of the Site.
3. Minimize waste and pollutants, conserve natural resources and energy, and recycle materials in every aspect of our operations, cleanup and closure of the Rocky Flats Site.
4. Educate our employees and subcontractors regarding responsible care of the environment and encourage their active participation to improve Kaiser-Hill performance.
5. Actively support community initiatives regarding responsible care of the environment.
6. Continually assess the environmental impacts and opportunities of our closure operations with a goal to of continuous improvement.
7. Maintain necessary emergency preparedness plans to address potential environmental hazards at RFETS
8. Measure and report environmental performance through self-evaluations, assessments and audits.
9. Assure subcontractors have strong environmental stewardship performance by including environment stewardship as an element of evaluation in procurement and performance.

Approved: _____


Robert G. Card, President

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Aqueous Process Sludge (IDC 0001)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D009 D010 F001			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G23			1
Management Method Code for Source Code G25			Density
W504			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	9,238.600000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
 Section 1, Box B, F002, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Second Stage Sludge (IDC 0002)		
	B. EPA Hazardous Waste Codes D004 D005 D009 D010 F001		C. State Hazardous Waste Codes
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W504	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site	ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 437.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F002, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Organic Waste Immobilization (IDC 0003)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D022 D026 D027 D029 D030			
D. Source Code G16 Management Method Code for Source Code G25	E. Form Code W403	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 4,914.400000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D032, D034, D037, F001, F002.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Bypass Sludge B374 (IDC 0007)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D002 F001			
F002 F005 F006			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15			
Management Method Code for Source Code G25			Density
W504			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	TXD988088464	H111	434.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	NM4890139088	H141	1,268.200000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Grease Oxide (Green Cake) (IDC 0089)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D007 NA			
NA NA NA			
D. Source Code G07		E. Form Code W319	F. Quantity Generated in reporting year
Management Method Code for Source Code G25			H. UOM 1
			Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 708.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Grease oxide
Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Grease Fluoride (IDC 0099)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D007 NA			
NA NA NA			
D. Source Code		E. Form Code	F. Quantity Generated in reporting year
G07			
Management Method Code for Source Code G25		W319	H. UOM 1
			Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	1,059.100000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Grease fluoride
 Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Filter Sludge (IDC 0290)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D007 D008 D009 F001			
D. Source Code G23 Management Method Code for Source Code G25	E. Form Code W504	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 6,468.200000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Incinerator Sludge (IDC 0292)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W519	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg.

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 93.500000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 27,771.200000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Incinerator sludge.
Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste are the following CERCLA waste numbers:
shipped in 2005: NM4 = 1451.4

Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Inorganic Sludge (IDC 0299)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D003 D004 D005 D007 D008				
D. Source Code G14 Management Method Code for Source Code G25		E. Form Code W504	F. Quantity Generated in reporting year 270,256.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 267,832.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 43,466.000000	
Site 3	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 45,689.000000	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 786830
shipped in 2005: UTD = 759986; TNR = 41730; NM4 = 1464.7.

Section 1, Box B, D009, D010, D011, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U106, U108, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Glass-Immobilized - Low Temperature - Fine Materials (IDC 0317)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D007 D008 NA NA NA			
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W319	F. Quantity Generated in reporting year
			H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 425.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Glass - Immobilized - Low Temperature - Fine Materials
 Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Heavy Non-SS Metal (TA, W, PT) (IDC 0320)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D008 NA			
NA NA NA			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15			
Management Method Code for Source Code G25			Density
W307			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	952.400000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Lead (IDC 0321)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D002 D004 D005 D006 D007			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W307	F. Quantity Generated in reporting year 2,557.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 5,749.000000
Site 2	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped 10,698.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 1090.8

Section 1, Box B, D008, D009, D010, D011, D022, D028, D029, F001, F002, F005, F006,
F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Mixed IDC's Outside PA (hazardous waste) Not d-38 (IDC 0324)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D002 D004			
D005 D006 D007			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15			1
Management Method Code for Source Code G25	W002	942,240.800000	Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	UTD982598898	H132	1,021,250.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 16

Waste Description: Mixed IDC's Outside PA (hazardous waste) Not d-38 (IDC 0324)

Supplemental Comments

Included in the above waste numbers are the following CERCLA waste numbers;
generated in 2005 = 432893.4
shipped in 2005: UTD = 468364.40

Section 1, Box B, D008, D009, D010, D011, D018, D019, D022, D027, D028, D029, D032, D033, D034, D035, D038, D039, D040, D042, D043, F001, F002, F005, F006, F007, F008, F009, F039, P011, P012, P015, P016, P022, P028, P030, P087, P098, P099, P106, P113, P119, P120, U002, U003, U004, U009, U027, U031, U044, U077, U078, U079, U080, U098, U103, U106, U108, U112, U113, U117, U123, U144, U145, U151, U154, U160, U161, U188, U204, U211, U213, U214, U215, U216, U217, U234, U359.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Mixed IDC's outside PSZ (Mixed Waste) (IDC 0325)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D002 D003 D004 D005 D006			
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year 21,720.000000 H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code Quantity treated, disposed or recycled on-site		On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 155,108.100000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 198.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 17

Waste Description: Mixed IDC's outside PSZ (Mixed Waste) (IDC 0325)

Supplemental Comments

Included in the above waste numbers are the following CERCLA waste numbers:

generated in 2005 = 21720

shipped in 2005: UTD = 108270.10; TXD = 198.00

Section 1, Box B, D007, D008, D009, D010, D011, D018, D028, D029, D035, D038, D039, D040, D043, F001, F002, F005, F007, F008, F009, P028, P030, P098, P099, P106, U002, U003, U009, U103, U108, U117, U123, U154, U160, U161, U188, U213, U234.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Filter, Ful-Flo, From Incinerator (IDC 0328)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W310	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 184.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Filters FulFlo, Not from incinerator (IDC 0331)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W310	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,559.700000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 484.50

Section 1, Box B, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009,
P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Oily Sludge (IDC 0332)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D007 D008 F001 F002 F005			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W603	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 682.000000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 3,526.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Absolute Drybox Filters, not acid contaminated (IDC 0335)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D004 D005 D006 D007			
D. Source Code G15	E. Form Code W310	F. Quantity Generated in reporting year 80.500000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg
Management Method Code for Source Code G25			

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 100.000000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 378.900000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

Section 1, Box B, D008, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustibles Wet (IDC 0336)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year 3,450.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code	Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,125.000000
Site 2	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped 3,852.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Plastic (Teflon, PVC, Poly, etc.) (IDC 0337)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15			1
Management Method Code for Source Code G25	W403	101.400000	Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	595.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	UTD982598898	H132	5,552.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Filter Media (IDC 0338)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005			
D006 D007 D008			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G13			
Management Method Code for Source Code G25			Density
W310			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	86.900000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Leaded Drybox gloves, not acid contaminated (IDC 0339)			
	B. EPA Hazardous Waste Codes D008 D022 D028 F001 F002		C. State Hazardous Waste Codes	
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002		F. Quantity Generated in reporting year 71.600000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site		ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 3,773.100000
	Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Fire Brick (IDC 0371)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,171.200000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Fire Brick Heel (IDC 0373)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 6,982.200000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Blacktop, concrete, dirt and sand (IDC 0374)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D005 D006 D007 D008 D011			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 39,767.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 5,908.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 486530
shipped in 2005: UTD = 1413895.16

Section 1, Box B, F001, F002, F005, F006, F007, F009, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Fire Brick, Coarse (IDC 0377)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 801.700000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Pulverized Incinerator Ash (IDC 0420)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W303	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 716.400000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: NM4 = 142.29

Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO.: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Insulation (IDC 0438)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F005 F006 F007			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 154.300000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Glass (Except Raschig Rings) (IDC 0440)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D005 D008 D009 D022 F001			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 174.200000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 737.100000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F002, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Rschig Rings, Solvent Contaminated (IDC 0443)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D005 D008 D009 D022 F001			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W319	F. Quantity Generated in reporting year 15,002.600000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 16,077.700000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 887.700000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Rasching Rings
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 14777.7
shipped in 2005: UTD = 14777

Section 1, Box B, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Ground/Leaded Glass (IDC 0444)		
B. EPA Hazardous Waste Codes D005 D008 D009 D022 F001		C. State Hazardous Waste Codes	
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 600.900000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 4,486.400000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: TXD = 376.00; NM4 = 623.40

Section 1, Box B, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Light Metal (IDC 0480)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code: G25	E. Form Code W307	F. Quantity Generated in reporting year 4,704.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 118,029.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 6,316.900000
Site 3	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 9,761.960000

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: TXD = 909.00; NM4 = 24240.00

Section 1, Box B, D009, D010, D011, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Glovebox Parts with Lead (IDC 0488)		
B. EPA Hazardous Waste Codes D008 NA NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W307	F. Quantity Generated in reporting year
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 1,283.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 1,726.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: TXD = 362.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description HEPA Filters (24x24), not Acid Contaminated (IDC 0490)		
B. EPA Hazardous Waste Codes D001 D004 D005 D006 D007		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W310	F. Quantity Generated in reporting year 896.000000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 1,425.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 5,008.000000
Site 3	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 1,429.000000

Comments:

Section 1, Box B, D008, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U025, U041, U042, U103, U108, U130, U162, U227, U359.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Prefilter (IDC 0491)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 F001			
F002 F005 F006			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15			
Management Method Code for Source Code G25			Density
W310			<input type="checkbox"/> lbs/gal. <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	TXD988088464	H111	117.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Neutral Waste Solution PH>2 but <12.5 (IDC 0505)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F005 F006 F007			
D. Source Code G23 Management Method Code for Source Code G25	E. Form Code W113	F. Quantity Generated in reporting year 4,876,240.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 4,876,240.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

Section 1, Box B, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Organic Solids (IDC 0523)		
	B. EPA Hazardous Waste Codes D004 D005 D007 D008 D009		
C. State Hazardous Waste Codes			
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W409	F. Quantity Generated in reporting year 6,976.200000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site	
ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped TNO890090004	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped (page 26) 109.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 23,945.200000
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 40

Waste Description: Miscellaneous Organic Solids (IDC 0523)

Supplemental Comments

Sec. 1, Box E: A generic solid or solidified material which primarily organic in composition.

Included in the above waste numbers are the following CERCLA waste numbers:

generated in 2005 = 375.2

shipped in 2005: TNO = 109.00; NM4 = 924.00

Section 1, Box B, D010, D022, D027, D028, D029, D032, D033, D034, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U002, U003, U004, U027, U031, U044, U077, U078, U079, U080, U103, U108, U112, U113, U123, U154, U159, U160, U161, U188.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Basic Waste Solution PH = or >12.5 (IDC 0527)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D002 D007				
NA NA NA				
D. Source Code G23		E. Form Code W110	F. Quantity Generated in reporting year	H. UOM 1
Management Method Code for Source Code G25				Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 436.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
 Included in the above waste numbers are the following CERCLA waste numbers:
 shipped in 2005: FLD = 436.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Organic Liquid/Solution (IDC 0529)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D010 F001 F002 F003			
D. Source Code G22 Management Method Code for Source Code G25		E. Form Code W219	F. Quantity Generated in reporting year 41.000000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input checked="" type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code H082		On-site Management Method Code NA
Quantity treated, disposed or recycled on-site 278.000000		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H061	D. Total quantity shipped (page 26) 1,705.300000
Site 2	B. EPA ID No. of facility to which waste was shipped TND982109142	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped 330.000000
Site 3	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 2,583.500000

Comments: Sec. 1, Box E: Ignitable liquid with heavy metals
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 714
shipped in 2005: FLD = 1004; TXD = 2583.5

Section 1, Box B, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Aqueous/Organic Liquid Mixture (IDC 0530)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
F001 F002				
NA NA NA				
D. Source Code G13		E. Form Code W204	F. Quantity Generated in reporting year 649.000000	H. UOM 1
Management Method Code for Source Code G25		Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg		

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H061	D. Total quantity shipped (page 26) 909.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: FLD = 909.0

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Organic Sludge (IDC 0531)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D005 D007 D008 D009			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W409	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 873.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Section 1, Box E: A viscous or semi-solid material which is primarily organic in composition
Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F001, F002, F003, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Organics-Disc Level-Cool Oil - Car Tet-Perchlor etc. (IDC 0533)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D001 D002				
D006 D007 D008				
D. Source Code G15		E. Form Code W204	F. Quantity Generated in reporting year	H. UOM 1
Management Method Code for Source Code G25				Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H061	D. Total quantity shipped (page 26) 4,947.900000	
Site 2	B. EPA ID No. of facility to which waste was shipped TND982109142	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped 761.000000	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 1587.00
shipped in 2005: FLD = 3089.40

Section 1, Box B, D010, D022, D028, D029, D043, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Excess Chemicals - Solid (IDC 0545)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D003 D004 D005 D006			
D. Source Code G11 Management Method Code for Source Code G25	E. Form Code W004	F. Quantity Generated in reporting year 335.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H061	D. Total quantity shipped (page 26) 800.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TND982109142	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped 23.000000
Site 3	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 767.800000

Comments: Section 1, Box B, D007, D008, D010, D011, D035, F008, P098, P120, U144.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

**FORM
GM**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solidified Sludge - Bldg. 774 (IDC 0800)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D007 D008 D009 D011			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W505	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 9,054.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

FORM
GM

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solidified Organics - Bldg. 774 (IDC 0801)		
	B. EPA Hazardous Waste Codes D022 D028 D029 D030 D032		
C. State Hazardous Waste Codes			
D. Source Code G41 Management Method Code for Source Code G25	E. Form Code W403	F. Quantity Generated in reporting year 8,732.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input checked="" type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site H129 463.000000	ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site NA

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
	Site 1	B. EPA ID No. of facility to which waste was shipped WAR000010355	C. Off-site Management Method Code Shipped to H112
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 274,458.100000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 2: Not reportable as H071-H124. Repackaging.

Section 1, Box B, D034, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solidified Lab Waste - Bldg. 774 (IDC 0802)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F005 F006 F007			
D. Source Code G22 Management Method Code for Source Code G25	E. Form Code W319	F. Quantity Generated in reporting year 1,435.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 621.400000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 55,087.400000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E solidified laboratory waste
CERCLA shipped in 2005: TXD = 621.40; NM4 = 10088.5

Section 1, Box B, F009, P030, P098, P099, P106, U003, U103.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solidified Sludge - Bldg. 374 (IDC 0803)			
B. EPA Hazardous Waste Codes		F001 F002 F005 F006 F007	C. State Hazardous Waste Codes	
D. Source Code G14 Management Method Code for Source Code G25		E. Form Code W319	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		Quantity treated, disposed or recycled on-site	On-site Management Method Code	
			Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,001.400000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box E: Sludge produced by the Building 374, process waste treatment system, direct cementation process.
 Sec. 1, Box F: quantity shipped was generated and managed in prior years.
 Section 1, Box B, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solidified Bypass Sludge - Bldg. 374 (IDC 0807)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F005 F006 F007			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W319	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 5,555.300000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 19,180.700000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 52

Waste Description: Solidified Bypass Sludge - Bldg. 374 (IDC 0807)

Supplemental Comments

Sec. 1, Box E: Sludge produced in the Building 374 process wastewater treatment process when bypassing the direct cementation process.

Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: TXD = 222.00

Section 1, Box B, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Cemented Resin (IDC 0809)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F005 F006 F007			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W403	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 564.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Granulated Type Filter Media (IDC 0812)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D010 D022 D034 F001 F002			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W310	F. Quantity Generated in reporting year 4,564.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped WAR000010355	C. Off-site Management Method Code Shipped to H112	D. Total quantity shipped (page 26) 4,564.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TND982109142	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped 355.000000
Site 3	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped 6,891.000000

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 4564.00
shipped in 2005: WAR = 4564.00; UTD = 5050.00

Section 1, Box B, F005, F039, P016, P106, U002, U003, U004, U027, U031, U044, U077, U078, U079, U080, U108, U112, U113, U123, U154, U159, U160, U161, U188, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description RCRA Regulated Sludge - LL Mixed Haz. Waste (IDC 0813)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002			
F005 F006 F007			
D. Source Code		E. Form Code	F. Quantity Generated in reporting year
G13			
Management Method Code for Source Code G25		W519	4,495.000000
			H. UOM 1
			Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	UTD982598898	H132	4,495.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 4404
 shipped in 2005: UTD = 4404

Section 1, Box B, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Filter Socks -- LL Mixed Haz. Waste (IDC 0814)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002 F039 NA NA			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G13			
Management Method Code for Source Code G25			Density
W310			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	UTD982598898	H132	258.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: UTD = 258.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Polymerized Organics - small containers (IDC 0816)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D004 D005 D006 D007 D008				
D. Source Code G14 Management Method Code for Source Code G25		E. Form Code W403	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		Quantity treated, disposed or recycled on-site		On-site Management Method Code
				Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 569.900000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D022, D026, D027, D028, D029, D030, D032, D036, D043, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustibles Dry TRU Waste (IDC 0821)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 266.700000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustibles Wet TRU Waste (IDC 0822)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year 1,860.000000 H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 3,651.400000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 1028.30

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Cemented Miscellaneous Sludge (IDC 0823)		
B. EPA Hazardous Waste Codes D003 F006 F008 NA NA		C. State Hazardous Waste Codes	
D. Source Code G14 Management Method Code for Source Code G25		E. Form Code W312	F. Quantity Generated in reporting year
			H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 607.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 8,062.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: TXD = 8062.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Light Metal TRU waste (IDC 0824)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W307	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 2,969.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 1549.00
shipped in 2005: NM4 = 12,853.00

Section 1, Box B, D009, D010, D011, D022, D028, D029, F001, F002, F005, F007, F009,
P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Plastic TRU Waste (IDC 0825)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005			
D006 D007 D008			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G13			
Management Method Code for Source Code G25		2,025.300000	Density
W403			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	3,755.200000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 155.30

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Polymerized organic (IDC 0827)		
B. EPA Hazardous Waste Codes D002 D004 D005 D006 D007		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W403	F. Quantity Generated in reporting year 109.500000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped WAR000013055	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 652.900000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 13,617.400000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: WAR = 512.60; NM4 = 3298.80

Section 1, Box B, D008, D009, D010, D011, D022, D026, D027, D028, D029, D030, D032, D034, D036, D043, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Polymerized Aqueous - drum (IDC 0828)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D009 D010 D022			
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W403	F. Quantity Generated in reporting year H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 878.700000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 40,353.800000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 4901.60

Section 1, Box B, D027, D028, D029, D032, D033, D034, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U106.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Polymierized Aqueous - small cans (IDC 0829)		
	B. EPA Hazardous Waste Codes D004 D005 D009 D010 D022		
D. Source Code G22 Management Method Code for Source Code G25		E. Form Code W403	F. Quantity Generated in reporting year
			H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
On-site Management Method Code		Quantity treated, disposed or recycled on-site
On-site Management Method Code		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 119.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 555.600000
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D027, D028, D029, D032, D033, D034, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustible Dry TRU MIXed Waste (NMC, NDA, Non-PSZ) (IDC 0831)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,427.400000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustible Wet TRU Mixed Waste (NMC, NDA, Non-PSZ) (IDC 0832)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year 3,791.100000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 12,148.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 725.77

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Plastic TRU Mixed Waste (NMC, NDA, Non-PSZ) (IDC 0833)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D004 D005				
D006 D007 D008				
D. Source Code		E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15				1
Management Method Code for Source Code G25		W002	1,806.000000	Density
				<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	5,280.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: NM4 = 363.60

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combustible Dry LL Mixed Waste (NMC, NDA, Non-PSZ) (IDC 0851)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D003 D004 D005 D006 D007			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15 Management Method Code for Source Code G25	W002	101,596.900000	1 Density <input type="checkbox"/> lbs/gal. <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	UTD982598898	H132	123,486.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	TXD988088464	H111	400.400000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 101596.90
shipped in 2005: UTD = 101596.90

Section 1, Box B, D008, D009, D010, D011, D022, D027, D028, D029, D034, D035, D039, D040, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108, U160, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Combsutibles Wet LL Mixed Waste (NMC, NDA, Non-PSZ) (IDC 0852)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D004 D005				
D006 D007 D008				
D. Source Code		E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15			40,269.500000	1
Management Method Code for Source Code G25		W002		Density
				<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?			
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code	Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?			
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)				
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)	
	UTD982598898	H132	61,004.700000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
	TXD988088464	H111	3,662.000000	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 40269.5
 shipped in 2005: UTD = 60402.5

Section 1, Box B, D009, D010, D011, D022, D028, D029, D034, D035, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Plastic LL Mixed Waste (NMC, NDA, < Non-PSZ) (IDC 0853)			
	B. EPA Hazardous Waste Codes D008 D011 F001 F002 F005		C. State Hazardous Waste Codes	
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site		ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 160,860.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 6,423.000000	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Ground Glass (IDC 0855)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D008 D009 NA NA NA			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W002	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 50,974.900000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: UTD = 2706.4

80

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description U-238(D-38) Oxide Low Level Waste (IDC 0869)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002			
F005 NA NA			
D. Source Code		E. Form Code	F. Quantity Generated in reporting year
G13			
Management Method Code for Source Code G25		W304	H. UOM 1
			Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	TNR000005397	H111	1,010.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Lead (IDC 1321)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D008 NA			
NA NA NA			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15			1
Management Method Code for Source Code G25			Density
W307			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)	
	<input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	CAT000646117	H132	50,320.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: CAT = 50320.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Hazard Mixed Waste Forms, Containing <=80% by Vol. of any one WFC (IDC 1325)		
	B. EPA Hazardous Waste Codes D006 D007 D008 D018 D029		
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W320	F. Quantity Generated in reporting year 69,454.000000
			H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site	ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 8,734.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped CAT000646117	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped 169,500.000000
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 69054
shipped in 2005: COD = 8334.00; CAT = 169500.00

Section 1, Box B, D035, D039, D040.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Plastics and Rubber (IDC 1337)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D007 D008 NA NA			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W403	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 300.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: COD = 300.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Blacktop, concrete, dirt or sand (IDC 1374)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D008 D039 D040 F001 F002			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G13			1
Management Method Code for Source Code G25		3,822,062.600000	Density
W002			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	CAT000646117	H132	169,410.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	COD980591184	H141	3,970.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	TXD000838896	H111	3,648,682.600000

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 3822062.60
 shipped in 2005: CAT = 169410.00; COD = 3970.00; TXD = 3648682.60
 Section 1, Box B, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Oil-Dri and other oil or coolant absorbent (IDC 1375)		
B. EPA Hazardous Waste Codes D018 NA NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W409	F. Quantity Generated in reporting year
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 4,960.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Oil-dri and other oil or coolant absorbent.
Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Organic Liquid Solution (IDC 1529)		
B. EPA Hazardous Waste Codes D001 F001 F002 F005 NA		C. State Hazardous Waste Codes	
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W219	F. Quantity Generated in reporting year H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 2,434.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: Any organic type of liquid or solution.
Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: COD = 3929.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Inorganic solids (IDC 1532)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D008 D011 NA NA			
D. Source Code G15 Management Method Code for Source Code G25	E. Form Code W319	F. Quantity Generated in reporting year 37,300.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped CAT000646117	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 37,300.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box E: A solid or slolidified material which is primarily inorganic in composition. Used when no other specific IDC is applicable.
Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 47180.0
shipped in 2005: CAT = 37300.00; COD = 9880.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Non Rad Org-Disc Level-Cool Oil-Car Tet (IDC 1533)			
	B. EPA Hazardous Waste Codes D008 F001 F002 NA NA		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W204	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site		ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 500.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: COD = 500.0

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Waste Excess Liquid Chemicals (IDC 1544)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D002 D003 D004 D005			
D. Source Code G11 Management Method Code for Source Code G25	E. Form Code W004	F. Quantity Generated in reporting year 24,991.000000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 26,285.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 20010.00
shipped in 2005: COD = 20649.00

Section 1, Box B, D006, D007, D008, D009, D011, D018, D019, D021, D022, D026, D027,
D028, D029, D033, D035, D039, D040, D043, P098, U003, U057, U075, U107, U122, U154,
U226, U239.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Waste Excess Solid Chemicals (IDC 1545)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D003 D005 D006 D008			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G11			1
Management Method Code for Source Code G25		1,604.000000	Density
W004			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	COD980191184	H141	1,667.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 342.00
 shipped in 2005: COD = 342.00

Section 1, Box B, D011, U135, U165.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Fluorescent Light Bulbs (IDC 1928)		
B. EPA Hazardous Waste Codes D009 NA NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G11 Management Method Code for Source Code G25		E. Form Code W320	F. Quantity Generated in reporting year 8,680.000000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 16,717.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 8206.00
shipped in 2005: COD = 16243.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Photographic Fixed (IDC 1930)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D011 NA			
NA NA NA			
D. Source Code G15	E. Form Code W113	F. Quantity Generated in reporting year 1,576.000000	H. UOM 1
Management Method Code for Source Code G25		Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 2,426.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 880.00
shipped in 2005: COD = 880.0

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Mercury/Sodium Vapor Lamps (IDC 1937)			
B. EPA Hazardous Waste Codes		D008 D009		C. State Hazardous Waste Codes
NA NA NA				
D. Source Code G15		E. Form Code W002	F. Quantity Generated in reporting year 991.000000	H. UOM 1
Management Method Code for Source Code G25		Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg		

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code	Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,135.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 827.00
 shipped in 2005: COD = 971.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Incandescent Bulbs (IDC 1938)			
B. EPA Hazardous Waste Codes		D008 NA		C. State Hazardous Waste Codes
NA NA NA				
D. Source Code G15		E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
Management Method Code for Source Code G25		W002	527.000000	Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 664.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 512.00
 shipped in 2005: COD = 649.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Oil/Coolant Mixture (IDC 1949)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D010 F001			
F002 NA NA			
D. Source Code G13		E. Form Code	F. Quantity Generated in reporting year
Management Method Code for Source Code G25		W205	491.000000
		H. UOM 1	
		Density	
		<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	COD980591184	H141	491.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 491.00
 shipped in 2005: COD = 491.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Coolants (IDC 1951)		
B. EPA Hazardous Waste Codes D010 NA NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G16 Management Method Code for Source Code G25		E. Form Code W205	F. Quantity Generated in reporting year 2,530.000000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 2,530.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 2024.00
shipped in 2005: COD = 2024.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Solvents (IDC 1952)			
	B. EPA Hazardous Waste Codes D039 NA NA NA NA			
C. State Hazardous Waste Codes		D. Source Code G13 Management Method Code for Source Code G25		
E. Form Code W113		F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
On-site Management Method Code		Quantity treated, disposed or recycled on-site
On-site Management Method Code		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
	Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Included in the above waste numbers are the following CERCLA waste numbers:
shipped in 2005: COD = 4422.0

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Water Filters, Not Ful-Flo (IDC 1960).		
B. EPA Hazardous Waste Codes F039 NA NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W310	F. Quantity Generated in reporting year
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 110.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Elemental Mercury (IDC 1969)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D009 NA				
NA NA NA				
D. Source Code G15		E. Form Code W117	F. Quantity Generated in reporting year 235.000000	H. UOM 1
Management Method Code for Source Code G25		Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg		

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		On-site Management Method Code		
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 235.000000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 235.0
shipped in 2005: COD = 235.0

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Batteries (IDC 1980)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D002 D006 D008 NA NA			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G16			1
Management Method Code for Source Code G25		10,262.000000	Density
W309			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	COD980591184	H141	14,592.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
 generated in 2005 = 10053.00
 shipped in 2005: COD = 14951.00; PAD = 49928.00

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Slightly Compressed TRU Mixed Combustable Waste (831, 832, 833) (IDC 2116)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15 Management Method Code for Source Code G25	W307	3,666.000000	1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 4,760.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

Section 1, Box B, D009, D010, D011, D018, D019, D022, D028, D029, D043, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Slightly Compressed TRU Combustable Waste (821, 822, 825) (IDC 2216)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
F001 F002			
F005 NA NA			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G15			1
Management Method Code for Source Code G25		3,755.000000	Density
W307			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No. (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	3,755.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Composite Debris 1-10% organic (IDC 3010)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D005 D008 D009 D011 F001			
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 2,167.700000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 11,173.100000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: TXD = 847.70; NM4 = 6801.30

Section 1, Box B, F002, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Composite Debris >10% (IDC 3011)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D004 D005				
D006 D007 D008				
D. Source Code		E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15				
Management Method Code for Source Code G25		W002		Density
				<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code
		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4880139088	H141	73,746.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	UTD982598898	H132	4,259.200000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	TXD988088464	H111	1,054.900000

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: NM4 = 47813.90; UTD = 4259.20; TXD = 1054.90

Section 1, Box B, D009, D010, D011, D022, D028, D029, F001, F002, F005, F006, F007, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Blended Incinerator Ash (IDC 420P)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G14 Management Method Code for Source Code G25	E. Form Code W303	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 4,244.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Mixed IDC/s - Surface Contaminated Objects (SC) (IDC 5001)			
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes		
D002 D004				
D005 D006 D007				
D. Source Code G15		E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
Management Method Code for Source Code G25		W002	3,891,590.000000	Density
				<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	TXD988088464	H111	43,320.610000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	NM4890139088	H141	472.000000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 99

Waste Description: Mixed IDC/s Surface Contaminated Objects (SC) (IDC 5001)

Supplemental Comments

Included in the above waste numbers are the following CERCLA waste numbers:

generated in 2005 = 1161027.65

shipped in 2005: UTD = 1166712.00; TXD = 472.00

Section 1, Box B, D008, D009, D010, D011, D022, D028, D029, D043, F001, F002, F005, F006, F007, F008, F009, F039, P015, P016, P022, P028, P030, P076, P087, P098, P099, P106, P113, P119, P120, U003, U020, U098, U103, U106, U108, U117, U123, U135, U160, U211, U214, U215, U216, U359.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Commingled SCO and LSA Waste (IDC5022)		
B. EPA Hazardous Waste Codes D005 D008 F001 F002 F005		C. State Hazardous Waste Codes	
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year 69,250.000000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 254,290.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 69250.00
shipped in 2005: UTD = 254290.00

Section 1, Box B, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Downblended Oxides, 10% contains Uranium (IDC 532A)			
B. EPA Hazardous Waste Codes		D007 D008		C. State Hazardous Waste Codes
NA NA NA				
D. Source Code G07		E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
Management Method Code for Source Code G25		W304		Density
				<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?			
<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)				
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code	Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?			
<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)				
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 743.800000	
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Downblended Oxides <10% may contain moisture (IDC 532B)		
	B. EPA Hazardous Waste Codes D006 D007 D008 NA NA		
C. State Hazardous Waste Codes			
D. Source Code G07 Management Method Code for Source Code G25		E. Form Code W304	F. Quantity Generated in reporting year
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1	
On-site Management Method Code		Quantity treated, disposed or recycled on-site
ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 705.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Downblended oxides <10%, downblended misc. oxides (IDC 532C)			
	B. EPA Hazardous Waste Codes D007 D008 NA NA NA		C. State Hazardous Waste Codes	
D. Source Code G07 Management Method Code for Source Code G25	E. Form Code W304	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
	ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site		ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 4,901.700000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped	

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Duct Holdup (IDC 0H61)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D007 D008 D009 D018			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
G13			1
Management Method Code for Source Code G25	W319	913.000000	Density
			<input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?	
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped (page 26)
	NM4890139088	H141	13,511.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

Section 1, Box B, D019, D022, D028, D029, D043, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Low Level TSAC Waste - PCB Liquids (IDC 0970)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D005 D006 D007 D008 D010			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15 Management Method Code for Source Code G25	W206		Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 9,364.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D011, F001, F002.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Miscellaneous Inorganic Solids (IDC 0532)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D001 D003 D005 D006 D007			
D. Source Code G41 Management Method Code for Source Code G25	E. Form Code W312	F. Quantity Generated in reporting year 68,253.700000	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 492.000000
Site 2	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 760.000000
Site 3	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 293.450000

Comments: Included in the above waste numbers are the following CERCLA waste numbers:
generated in 2005 = 596.70
shipped in 2005: UTD = 180.00; TNR = 428.90; NM4 1059.40

Section 1, Box B, D008, D009, D010, D028, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME:

EPA ID NO:



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM
Management Method Code for Source Code G25			Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code NA Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input type="checkbox"/> Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 15,056.750000
Site 2	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 996.400000
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
GM**

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description D & D LSA Combined IDCs (IDC 0322)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D007 D008 D009 D011			
D. Source Code	E. Form Code	F. Quantity Generated in reporting year	H. UOM 1
G15 Management Method Code for Source Code G25	W002	2,079,509.000000	Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped WAR000010355	C. Off-site Management Method Code Shipped to H112	D. Total quantity shipped (page 26) 1,136.000000
Site 2	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped 3,027,889.000000
Site 3	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 41,260.000000

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 107

Waste Description: D & D LSA Combined IDCs (IDC 0322)

Supplemental Comments

Sec. 3, Box B continued on supplemental page.

Included in the above waste numbers are the following CERCLA waste numbers:

generated 2005 = 20821631.00

shipped 2005: WAR = 168406.00; UTD = 21174421.00; TNR = 41260.00; TXD =
12562200.00

Section 1, Box B, D022, D033, D039, D040, F001, F002, F005, F006, F007, F009, P030, P098,
P099, P106, U003, U103, U108, U211.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME:

EPA ID NO:



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description		
	B. EPA Hazardous Waste Codes		
C. State Hazardous Waste Codes		D. Source Code	
E. Form Code		F. Quantity Generated in reporting year.	H. UOM
Management Method Code for Source Code G25			Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site?		
	<input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code		On-site Management Method Code	
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site	
		NA	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling?		
	<input type="checkbox"/> Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TXD988088464	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped (page 26) 72,410.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Excess Chemicals - Liquid (IDC 0544)		
B. EPA Hazardous Waste Codes D001 D002 D003 D004 D005		C. State Hazardous Waste Codes	
D. Source Code G11 Management Method Code for Source Code G25		E. Form Code W004	F. Quantity Generated in reporting year 1,845.700000
		H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg	

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code		On-site Management Method Code	
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped TND982109142	C. Off-site Management Method Code Shipped to H040	D. Total quantity shipped (page 26) 117.700000
Site 2	B. EPA ID No. of facility to which waste was shipped FLD980711071	C. Off-site Management Method Code Shipped to H061	D. Total quantity shipped 5,125.000000
Site 3	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 987.000000

Comments:

See supplemental comment page for full comments.

Supplemental Comments Required for the GM Reports

GM Page # 108

Waste Description: Excess Chemicals - Liquid (IDC 0544)

Supplemental Comments

Sec. 3, Box B continued on supplemental page

Section 1, Box B, D006, D007, D008, D009, D010, D011, D018, D019, D022, D026, D027, D028, D029, D035, D038, D039, D040, F001, F002, F003, F004, F005, F008, P098, U002, U028, U044, U050, U069, U071, U077, U080, U083, U107, U108, U121, U134, U151, U154, U210, U211, U226, U228, U239, U240.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME:

EPA ID NO:



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D. Source Code Management Method Code for Source Code G25	E. Form Code	F. Quantity Generated in reporting year	H. UOM Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)		
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site Management Method Code		On-site Management Method Code	
Quantity treated, disposed or recycled on-site		Quantity treated, disposed or recycled on-site	
		NA	

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input type="checkbox"/> Yes (CONTINUE TO BOX B) <input checked="" type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped COD980591184	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 253.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Sludge From Size Reduction Area (IDC 0340)			
B. EPA Hazardous Waste Codes		D006 D007 D008 D009 D011		C. State Hazardous Waste Codes
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W506	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)			
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2		
On-site Management Method Code		Quantity treated, disposed or recycled on-site		
On-site Management Method Code		Quantity treated, disposed or recycled on-site		

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 12,474.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Absolute DryBox Filters, Acid Contaminated (IDC 342)			
B. EPA Hazardous Waste Codes D004 D005 D006 D007 D008		C. State Hazardous Waste Codes		
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W310	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1 On-site Management Method Code Quantity treated, disposed or recycled on-site		ON-SITE PROCESS SYSTEM 2 On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 268.200000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Grit (IDC 0372)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D007 NA			
NA NA NA			
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W307	F. Quantity Generated in reporting year
			H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 1,148.800000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: NM4 = 442.5

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Oil Dry (IDC 0375)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D006 D007 D008 D009 D010			
D. Source Code G13 Management Method Code for Source Code G25		E. Form Code W310	F. Quantity Generated in reporting year H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 99.000000
Site 2	B. EPA ID No. of facility to which waste was shipped TNR000005397	C. Off-site Management Method Code Shipped to H111	D. Total quantity shipped 676.000000
Site 3	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped 270.000000

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years. Included in the above waste numbers are the following CERCLA waste numbers: shipped in 2005: UTD = 79.00; TNR = 166.00
Section 1, Box B, D018, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Processed Filter Media (IDC 0376)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G13 Management Method Code for Source Code G25	E. Form Code W310	F. Quantity Generated in reporting year	H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 129.000000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.

Section 1, Box B, D009, D010, D011, D022, D029, F001, F002, F005, F006, F007, F009, P030, P098, P099, P106, U003, U103, U108.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**FORM
GM**

**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**WASTE GENERATION
AND MANAGEMENT**

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Fire Bricks, Pulverized or Fines (IDC 0378)		
B. EPA Hazardous Waste Codes		C. State Hazardous Waste Codes	
D004 D005 D006 D007 D008			
D. Source Code G15 Management Method Code for Source Code G25		E. Form Code W002	F. Quantity Generated in reporting year H. UOM 1 Density <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2
On-site Management Method Code	Quantity treated, disposed or recycled on-site	On-site Management Method Code Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)		
Site 1	B. EPA ID No. of facility to which waste was shipped NM4890139088	C. Off-site Management Method Code Shipped to H141	D. Total quantity shipped (page 26) 207.500000
Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, D009, D010, F001, F002, F005.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



FORM
GM

U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

WASTE GENERATION
AND MANAGEMENT

Instructions: Please see the detailed instructions on pages 17 to 25 of the instructions and forms booklet before completing this form.

Sec. 1	A. Waste Description Resin, Leached (IDC 0431)		
	B. EPA Hazardous Waste Codes F001 F002 F005 F006 F007		
D. Source Code G08 Management Method Code for Source Code G25		E. Form Code W310	F. Quantity Generated in reporting year
			H. UOM 1 Density. <input type="checkbox"/> lbs/gal <input type="checkbox"/> sg

Sec. 2	Was any of this waste managed on-site? <input type="checkbox"/> Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) <input checked="" type="checkbox"/> No (SKIP TO SEC. 3)	
	ON-SITE PROCESS SYSTEM 1	ON-SITE PROCESS SYSTEM 2
On-site Management Method Code		Quantity treated, disposed or recycled on-site
On-site Management Method Code		Quantity treated, disposed or recycled on-site

Sec. 3	A. Was any of this waste shipped off-site for treatment, disposal or recycling? <input checked="" type="checkbox"/> Yes (CONTINUE TO BOX B) <input type="checkbox"/> No (FORM IS COMPLETE)			
	Site 1	B. EPA ID No. of facility to which waste was shipped UTD982598898	C. Off-site Management Method Code Shipped to H132	D. Total quantity shipped (page 26) 140.000000
	Site 2	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped
	Site 3	B. EPA ID No. of facility to which waste was shipped	C. Off-site Management Method Code Shipped to	D. Total quantity shipped

Comments: Sec. 1, Box F: quantity shipped was generated and managed in prior years.
Section 1, Box B, F009.

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
OI**

**OFF-SITE
IDENTIFICATION**

Instructions: Please read the detailed instructions on the reverse side before completing this form.

Site 1	A. EPA ID No. of off-site installation or transporter UTD982598898	B. Name of off-site installation or transporter Envirocare of Utah, Inc.
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 46 West Broadway, Suite 240 City Salt Lake State UT Zip 84101
Site 2	A. EPA ID No. of off-site installation or transporter COD980591184	B. Name of off-site installation or transporter Onyx
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 9131 E. 96th Avenue City Henderson State CO Zip 80640
Site 3	A. EPA ID No. of off-site installation or transporter NM4890139088	B. Name of off-site installation or transporter Waste Isolation Pilot Plant
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street WIPP Site, JAL Highway City Carlsbad State NM Zip 88221
Site 4	A. EPA ID No. of off-site installation or transporter WAR000010355	B. Name of off-site installation or transporter Pacific EcoSolutions - PEcos
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 2025 Batelle Blvd. City Richland State WA Zip 99352
Site 5	A. EPA ID No. of off-site installation or transporter FLD980711071	B. Name of off-site installation or transporter Perma-Fix Environmental Services
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 1940 NW 67th Place City Gainesville State FL Zip 32653

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: CO7890010526



U.S. ENVIRONMENTAL
PROTECTION AGENCY

Hazardous Waste Report

FORM
OI

OFF-SITE
IDENTIFICATION

Instructions: Please read the detailed instructions on the reverse side before completing this form.

Site 1	A. EPA ID No. of off-site installation or transporter TNO890090004	B. Name of off-site installation or transporter US DOE Oakridge
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility	D. Address of off-site installation Street ETPP HIWY 58 & Blair Road City Oakridge State TN Zip 37831	
Site 2	A. EPA ID No. of off-site installation or transporter CAT000646117	B. Name of off-site installation or transporter Chemical Waste Management, Inc. - Kettleman
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility	D. Address of off-site installation Street 35251 Old Skyline Road City Kettleman City State CA Zip 93239-0471	
Site 3	A. EPA ID No. of off-site installation or transporter TNR000005397	B. Name of off-site installation or transporter Perma-Fix - Materials & Energy Corp.
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility	D. Address of off-site installation Street 2010 Highway 58 Suite 1020 City Oak Ridge State TN Zip 37830	
Site 4	A. EPA ID No. of off-site installation or transporter ID4890008952	B. Name of off-site installation or transporter Argonne National Laboratory - West
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility	D. Address of off-site installation Street P. O. Box 2528 City Idaho Falls State ID Zip 83403-2528	
Site 5	A. EPA ID No. of off-site installation or transporter TXD988088464	B. Name of off-site installation or transporter Waste Control Specialists
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility	D. Address of off-site installation Street 1710 West Broadway/9998 W. State Highway 176 City Andrews State TX Zip 79714	

Comments:

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Rocky Flats Env. Tech. Site-US

EPA ID NO: C07890010526



**U.S. ENVIRONMENTAL
PROTECTION AGENCY**

Hazardous Waste Report

**FORM
OI**

**OFF-SITE
IDENTIFICATION**

Instructions: Please read the detailed instructions on the reverse side before completing this form.

Site 1	A. EPA ID No. of off-site installation or transporter TND982109142	B. Name of off-site installation or transporter Diversified Scientific Services, Inc - DSSI
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 657 Ballaher Raod City Kingston State TN Zip 37763
Site 2	A. EPA ID No. of off-site installation or transporter PAD990753089	B. Name of off-site installation or transporter EXIDE Technologies
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 3000 Montrose Avenue City Reading State PA Zip 19605
Site 3	A. EPA ID No. of off-site installation or transporter ILD098642424	B. Name of off-site installation or transporter Trade Waste Incinerator
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street 7 Mobile Avenue City Sauget State IL Zip 62201
Site 4	A. EPA ID No. of off-site installation or transporter TXD000838896	B. Name of off-site installation or transporter Onyx Environmental Services, LLC
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input checked="" type="checkbox"/> TSDR facility		D. Address of off-site installation Street Highway 73, 3.5 miles west of Tayler Bayou City Port Arthur State TX Zip 77640
Site 5	A. EPA ID No. of off-site installation or transporter	B. Name of off-site installation or transporter
C. Handler type (CHECK ALL THAT APPLY) <input type="checkbox"/> Generator <input type="checkbox"/> Transporter <input type="checkbox"/> TSDR facility		D. Address of off-site installation Street City State Zip

Comments:

131/131